

The background image shows an industrial site, likely a gas processing or distribution station. It features a complex network of large, yellow-painted pipes and valves. Two workers in blue uniforms and hard hats are visible: one in the middle ground and another in the foreground walking towards the camera. The ground is paved with grey bricks. In the background, there are green trees, a fence, and distant hills under a clear sky. A yellow banner is at the top of the image.

电仪检测专家

济宁鲁科

合作伙伴

>>>


济宁鲁科

让最先进的检测方案更广泛的服务于社会



射线探伤

沟槽对比试块



用于射线探伤时测量缺陷的深度

符合国家NB/T47013.2-2015相关标准



NB/T 47013.2—2015




图 L.2 II型对比试块

表 L.1 II型对比试块的尺寸

单位为 mm

h_1	h_2	h_3	h_4	尺寸偏差
0.3	0.5	1.0	1.5	± 0.05



压力管道



压力容器



船舶工业



石油石化



航空航天



电力设备



工业制造



高校科研



钢结构



军工



核电



铁路